Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-2102/1

Work Order Type: Weatherization

Audit Name: Audit (125)

CLIENT INFORMATION

Client Name: N/A Address:

Client ID: 17017UC-2102

Alt. Client ID: CLAY

CLIENT CONTACT INFORMATION

N/A Applicant/Person of ✓

Record

AGENCY INFORMATION

Agency: Upper Cumberland Human Resource Agency Agency Phone: (931) 528-1127

Address: 580 South Jefferson Avenue, Suite B Fax: (931) 526-8305

Cookville, TN 38501 *Email Address:*

Agency Contact: Smith, Richmond Work Phone:

Cell Phone: Email Address:

Company Name & License Number:

Contractor's Signature:

COMMENT

HOME BUILT IN 1968

AUDITOR: RICHMOND SMITH

Client Name: N/A
Client ID: 17017UC-2102
Alt. Client ID: CLAY

Work Order Name: WO/17017UC-2102/1 Report Run On: 4/9/2012

Version 8.6.0 Page 1 of 6

Measures

Measure 1 Seal Ducts				Compone		Inspected		
Comment SEAL D	OUCT & REGISTERS IN	N BR1 & BR	2.					
				Estimate	d		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Su	Duct Sealing	Each	1					
Other Detail								
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
Measure 2 Infilt	ration Redctn			Compone	nts			Inspected
	CE 10 X 10 AREA OF S	STAPLE UP		•		/AY.		
CAULK	INTERIOR OF ALL 11	WINDOWS	. REP	LACE DR1	& DR2 V	V/INS		
	DOOR UNITS AND ALI SLAB DOOR AND ALL						:	
	OR DOOR UNIT AND A						<u>.</u>	
			`	Estimate		,	Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscellaneous Su	Infiltration Reduction	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

	r-Spec Ceiling R			Componen	ts ATC1			Inspected
Comment SEAL &	R30 EXISTING ATTIC H	ATCH						
			Estimated Actual			Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Cellulose, Blown - R-30	SqFt	912					
2 Labor	Attic Insulation - Cellulose, Blown - R-30	SqFt	912					
3 Miscellaneous Su	Added Misc Cost - Cellulose, Blown - R-30	Each	1					
Other Detail								
			Measur	e Sub Total:]	Sub Total:	
Measure 4 DWI Comment	H Tank Insulation			Componen				Inspected
Comment				Estimated	1		Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	-		Qty	Actual Unit Cost	Inspected Total
Comment # Material / Labor		<i>Units</i> Each		Estimated	1	Qty		
	Description / Comment		Qty	Estimated	1	Qty		
Comment# Material / Labor1 Hot Water Equip	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty		
Comment# Material / Labor1 Hot Water Equip2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty		
Comment# Material / Labor1 Hot Water Equip2 Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty		
Comment# Material / Labor1 Hot Water Equip2 Labor	Description / Comment DHW Tank Insulation	Each Each	Qty 1 1	Estimated	1			

Report Run On: 4/9/2012

	<i>Measur</i> e 5 Ligh	ting Retrofits			Componer	its L1,L2			Inspected
C	Comment								
					Estimated	1			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Lighting	Compact Fl 13 Watt	Each Lamp	3					
2	Labor	Compact Fl 13 Watt	Each Lamp	3					
3	Lighting	Compact Fl 13 Watt	Each Lamp	3					
4	Labor	Compact FI 13 Watt	Each Lamp	3					
(Other Detail								
				Measur	e Sub Total:] ;	Sub Total:	
	Measure 6 DWF	•			Componer	nts			Inspected
C	comment WRAP 6	FT HOT & COLD LIN	ES @ W/H	IR	Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1		DHW Pipe Insulation	Each	1					
2	Labor	DHW Pipe Insulation	Each	1					
(Other Detail				. <u> </u>				
L									
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								

Report Run On: 4/9/2012

Measure 7 CO N	Nonitor is Needed			Componen	ts		ı	Inspecte
Comment								
				Estimated	1	Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Health and Safety	CO monitor	Each	1					
2 Labor	Labor	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
	sureRelief Piping Need	ded		Componen	ts			Inspecte
	sureRelief Piping Need	ded		Componen Estimated			Actual	Inspecte
Measure 8 Press Comment # Material / Labor	sureRelief Piping Need Description / Comment	ded <i>Unit</i> s	Qty	•		Qty		Inspecte
Comment # Material / Labor	, -			Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor 1 Health and Safety	Description / Comment	Units	Qty	Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor 1 Health and Safety 2 Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor 1 Health and Safety	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety2 Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
# Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	Units Each Each	Qty 1 1	Estimated	<u> </u>		Actual	
# Material / Labor 1 Health and Safety 2 Labor Other Detail	Description / Comment Pressure relief piping	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	Units Each Each	Qty 1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 9 Smoke Detector is Needed X 2			Componen	ts		Inspected		
Comment INSTAL	L 2 SMOKE DETECTOR	RS						
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	See the User Defined Measure for a list of materials.	Each	1					
Other Detail				1		1		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	der Gra	and Total:		Gran	d Total:	